

IBEW LOCAL UNION 112
TOOL LIST

As per Article3, Section 3.21 of the Basic Inside Agreement, Journeymen shall provide themselves with the following tools:

Tool belt and tool pouch	1 electrician hammer
2 pair channelocks	Electrician's knife
Wire strippers	Allen wrenches up to 3/8"
600 volt pouch type voltage tester	#2 lock recess driver
1 torpedo level	1 pair needle nose pliers
Six foot wood rule	Hacksaw frame
1 pair side cutting dikes	Tool box
1 pair side cutting pliers	Current NEC book
Combination square	
Steel tape, 25' or less, in addition a wooden is OK	
Seven (7) piece spin tites set up to 1/2"	
3/8", 7/16", 1/2", 9/16" combination wrenches	
Up to 7 screwdrivers, multi-bit drivers may be included	

"No Dog" levels and pocket type calculators are acceptable, but not required.

Revised 6/2018

IBEW LOCAL UNION 112
TOOL LIST

As per Article3, Section 3.21 of the Basic Inside Agreement, Journeymen shall provide themselves with the following tools:

Tool belt and tool pouch	1 electrician hammer
2 pair channelocks	Electrician's knife
Wire strippers	Allen wrenches up to 3/8"
600 volt pouch type voltage tester	#2 lock recess driver
1 torpedo level	1 pair needle nose pliers
Six foot wood rule	Hacksaw frame
1 pair side cutting dikes	Tool box
1 pair side cutting pliers	Current NEC book
Combination square	
Steel tape, 25' or less, in addition a wooden is OK	
Seven (7) piece spin tites set up to 1/2"	
3/8", 7/16", 1/2", 9/16" combination wrenches	
Up to 7 screwdrivers, multi-bit drivers may be included	

"No Dog" levels and pocket type calculators are acceptable, but not required.

Revised 6/2018